

## General Information

Date & Time: 20, Jan, 2026 19:18

<b>Make</b>	Toyota	<b>Model</b>	Hiace
<b>YOM</b>	2024	<b>Odo Meter Reading</b>	48,035
<b>Registration No.</b>	DBN3083	<b>Chassis No.</b>	JTFJT02P5P5035241
<b>CC</b>	3.0	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	Van
<b>Colour</b>	White		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	78.9	83	72	82
2	Boot Lid	71.3	66	79	69
3	Roof	66.1	75	65	58/67
4	Left Front Fender	76.9	68	85	78
5	Left Front Door	63.7	68	64	60
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	65.2	63	66	67
9	Right Front Fender	75.0	65	80	80
10	Right Front Door	63.8	63	63	66
11	Center Panel Right	74.3	84	75	64
12	Right Rear Door	66.3	67	70	62
13	Right Back Panel	75.8	71	80	77

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">E</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> (L) Front Floor Mat - Worked - Large / Overall Interior - Worn as per age - Yes / (L) Rear Trim - Worked - Large / (R) Rear Trim - Worked - Large / Ceiling - Grime - Large</p>	<p><b>Remarks</b> Front Bumper, Grille, Lamps - Scratch &amp; Dent - Large / (R) Front Door, Molding - Scratch &amp; Dent - Large / (R) Center Panel - Scratch - Medium / (R) Rear Door, Molding - Scratch &amp; Dent - Large / (R) Rear Fender, Molding - Scratch &amp; Dent - Large / Rear Bumper, Lamps, Panels - Scratch &amp; Dent - Large / Trunk Hood, Rear Gate - Scratch - Large / (L) Rear Fender, Molding - Scratch &amp; Dent - Large / (L) Rear Door, Molding - Scratch &amp; Dent - Large / (L) Front Door, Molding - Scratch - Medium</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>no warranty booklet/ no sparetire and jack/ no tools/ with LTO plate</p>