

## General Information

Date & Time: 21, Jan, 2026 10:01

<b>Make</b>	Toyota	<b>Model</b>	Fortuner
<b>YOM</b>	2021	<b>Odo Meter Reading</b>	51,527
<b>Registration No.</b>	NEO3115	<b>Chassis No.</b>	MHFCB8GS8M0520308
<b>CC</b>	2.4	<b>Transmission</b>	A/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	SUV
<b>Colour</b>	White		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	97.7	100	100	94
2	Boot Lid	87.4	81	100	82
3	Roof	103.7	90	107	126/92
4	Left Front Fender	91.9	100	88	88
5	Left Front Door	92.3	99	93	85
6	Center Panel Left				
7	Left Rear Door	83.4	89	84	78
8	Left Back Panel	92.8	93	94	92
9	Right Front Fender	91.3	86	89	99
10	Right Front Door	82.7	83	83	82
11	Center Panel Right				
12	Right Rear Door	82.7	86	81	81
13	Right Back Panel	100.3	99	92	110

## Overall Evaluation :

**D**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right;"><b>E</b></span>	<b>Exterior Evaluation :</b> <span style="float: right;"><b>E</b></span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> (R) Front Seat - Grime - Medium / (R) Front Trim - Grime - Large / (R) Rear Trim - Grime - Large / Rear Seat - Grime - Medium / Trunk Room - Worn, Scratch, Cut, Crack - Small / (L) Rear Trim - Grime - Medium / (L) Front Trim - Grime - Large / (L) Front Seat - Grime - Medium / Ceiling - Grime - Medium / Steering Wheel - Worn, Peel, Crack - Small / Console, Switchs, Vents - Worn, Scratch, Cut, Crack - Medium</p>	<p><b>Remarks</b> (L) Front Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch &amp; Dent - Small / (L) Rear Door, Molding - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Large / Trunk Hood, Rear Gate - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Rust, Corrosion - Medium / (R) Rear Door, Molding - Scratch &amp; Dent - Small / (R) Rear Fender, Molding - Scratch - Medium / Roof - Scratch - Small</p>
<b>Frame Evaluation :</b> <span style="float: right;"><b>A</b></span>	<b>Functional Evaluation :</b> <span style="float: right;"><b>B</b></span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Battery - Weak - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Horn - Issue - Yes</p>

<p><b>Inspector Notes</b></p>
<p>with LTO plate/with spare tire/with 1 spare tire/No jack and tools/with reverse camera/No warranty booklets/No fog light/plate light issue/possible flooding/No horn/interior dirty/No seat cover/unusual sound engine</p>