

## General Information

Date & Time: 19, Jan, 2026 13:57

<b>Make</b>	Toyota	<b>Model</b>	Hiace
<b>YOM</b>	2021	<b>Odo Meter Reading</b>	107,825
<b>Registration No.</b>	NGB8029	<b>Chassis No.</b>	JTFJ02P7L5024221
<b>CC</b>	3.0	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	Van
<b>Colour</b>	Silver		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	125.6	111	111	155
2	Boot Lid	109.3	110	113	105
3	Roof	113.0	112	115	109/116
4	Left Front Fender	746.6	653	1,010	577
5	Left Front Door	151.6	191	139	125
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	96.9	98	91	102
9	Right Front Fender	128.0	125	127	132
10	Right Front Door	111.6	119	108	108
11	Center Panel Right	108.4	98	108	119
12	Right Rear Door	104.3	103	103	107
13	Right Back Panel	120.3	133	118	110

## Overall Evaluation :

**D**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b>	C	<b>Exterior Evaluation :</b>	E
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>		<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>	
<p><b>Remarks</b> Ceiling - Loose, Deformed - Medium / (L) Front Seat - Cut, Crack - Small / Rear Seat - Missing - Yes / Carpet - Loose, Deformed - Large</p>		<p><b>Remarks</b> (R) Front Door - Repair Traces - Yes / (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Rear Fender - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / (R) Center Panel - Repair Traces - Yes / Roof - Repair Traces - Yes / (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch &amp; Dent - Small / (R) Center Panel - Scratch &amp; Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch &amp; Dent - Large / (R) Rear Door, Molding - Scratch &amp; Dent - Large / (R) Rear Fender, Molding - Scratch &amp; Dent - Large / Rear Bumper, Lamps, Panels - Crack, Gap - Large / Trunk Hood, Rear Gate - Scratch &amp; Dent - Small / (L) Rear Fender, Molding - Scratch &amp; Dent - Medium / (L) Front Door, Molding - Repair mark - Yes / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Repair mark - Yes / Front Bumper, Grille, Lamps - Crack, Gap - Medium / Bonnet, Headlight - Scratch &amp; Dent - Minimal / Roof - Dent - Medium</p>	
<b>Frame Evaluation :</b>	C	<b>Functional Evaluation :</b>	C
<p><b>Remarks</b> Front Cross Member Support - Traces of Bending, or Marks of Panel Repair ? - Yes / Left Front Inside Panel (Front Side) - Traces of Bending, or Marks of Panel Repair ? - Yes / Rear Side Member &amp; Trunk Room Floor - Traces of Bending, or Marks of Panel Repair ? - Yes</p>		<p><b>Remarks</b> Air Conditioner - Function - Weak / Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist</p>	

<b>Inspector Notes</b>
With Lto plate, with spare tire and jack, 1key, no warranty booklet and tools, scratches on headlights, Crack on taillights, aircon issue, rear seats missing