

General Information

Date & Time: 21, Jan, 2026 13:52

Make	Toyota	Model	Avanza
YOM	2023	Odo Meter Reading	105,075
Registration No.	NII4426	Chassis No.	MHFAA1BY4N0011332
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	MPV
Colour	Red Mica Metallic		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	221.6	230	226	209
2	Boot Lid	132.6	152	137	109
3	Roof	115.0	126	117	100/117
4	Left Front Fender	108.6	110	99	117
5	Left Front Door	118.6	116	114	126
6	Center Panel Left				
7	Left Rear Door	114.6	124	109	111
8	Left Back Panel	125.3	129	124	123
9	Right Front Fender	268.6	188	289	329
10	Right Front Door	113.0	120	109	110
11	Center Panel Right				
12	Right Rear Door	180.0	244	146	150
13	Right Back Panel	176.3	188	170	171

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Medium / (L) Front Seat - Worn - Yes / Overall Interior - Worn as per age - Yes / Overall Interior - Smell - Yes / Rear Seat - Grime - Medium / Ceiling - Grime - Small</p>	<p>Remarks (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / (R) Mirror - Scratch - Small / (R) Front Fender, Molding - Dent - Small / (R) Front Door, Molding - Scratch - Large / (R) Rear Door, Molding - Scratch - Large / (R) Rear Fender, Molding - Scratch - Large / Trunk Hood, Rear Gate - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Mirror - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch & Dent - Medium / (L) Rear Door, Molding - Scratch - Medium / (L) Front Fender, Molding - Repair mark - Yes / (R) Front Door, Molding - Repair mark - Yes / (L) Front Fender, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Repair mark - Yes / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Bonnet, Headlight - Scratch - Medium / Roof - Scratch & Dent - Medium / (L) Rear Fender, Molding - Repair mark - Yes / Trunk Hood, Rear Gate - Repair mark - Yes</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Door Lock - Issue - Yes / Head Light, High Beam - Issue - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes</p>

<p>Inspector Notes</p>
<p>with warranty booklet, jack, incomplete tools, with spare tire, with LTO plate, scratches on tail light, headlight lever switch issue, fog lamps and plate light issue, possible flooding, rear door hard to open</p>