

## General Information

Date & Time: 22, Jan, 2026 14:03

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2023	<b>Odo Meter Reading</b>	92,344
<b>Registration No.</b>	NHI7600	<b>Chassis No.</b>	PA1B18F34P4211117
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Blue		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	106.5	121	100	99
2	Boot Lid	100.3	96	94	111
3	Roof	91.3	99	88	88/90
4	Left Front Fender	92.8	96	92	91
5	Left Front Door	95.6	94	98	95
6	Center Panel Left				
7	Left Rear Door	100.0	100	99	101
8	Left Back Panel	100.5	105	102	95
9	Right Front Fender	96.8	104	92	94
10	Right Front Door	103.3	96	115	99
11	Center Panel Right				
12	Right Rear Door	99.7	92	103	104
13	Right Back Panel	96.3	89	100	100

## Overall Evaluation :

**D**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right;"><b>D</b></span>	<b>Exterior Evaluation :</b> <span style="float: right;"><b>D</b></span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<b>Remarks</b> (R) Front Seat - Grime - Large / (R) Front Trim - Grime - Small / (L) Front Floor Mat - Missing - Yes / Rear Seat - Grime - Large / Mat Other - Missing - Yes / (R) Front Floor Mat - Missing - Yes / (R) Rear Trim - Grime - Minimal / Trunk Room - Worn, Scratch, Cut, Crack - Small / (L) Rear Trim - Grime - Small / (L) Front Trim - Grime - Medium / (L) Front Seat - Grime - Medium / Dashboard - Traces of Adhesive Tape - Yes / Ceiling - Grime - Small / Console, Switchs, Vents - Worn, Scratch, Cut, Crack - Minimal	<b>Remarks</b> (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Small / (R) Front Fender, Molding - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch - Medium / (L) Front Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Medium / (R) Mirror - Scratch - Minimal / Roof - Scratch & Dent - Small
<b>Frame Evaluation :</b> <span style="float: right;"><b>A</b></span>	<b>Functional Evaluation :</b> <span style="float: right;"><b>C</b></span>
<b>Remarks</b> Defects not found	<b>Remarks</b> Air Conditioner - Function - Weak / Battery - Weak - Yes / Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Seat Belts - Issue - Yes

<b>Inspector Notes</b>
with LTO plate/with spare tire/with 2 spare key/with incomplete tools No jack /No reverse camera/radiator cover missing/trunk room cover missing/park light issue/with warranty booklet/plate light issue/aircon issue/seatbelts issue