

## General Information

Date & Time: 27, Jan, 2026 15:45

<b>Make</b>	Toyota	<b>Model</b>	Hilux Tamaraw
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	20,623
<b>Registration No.</b>	DBT8510	<b>Chassis No.</b>	PAHACACA7S6421855
<b>CC</b>	2.4	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	Dropside
<b>Colour</b>	White		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	88.9	90	87	89
2	Boot Lid	68.1	63	67	74
3	Roof	103.3	117	110	91/96
4	Left Front Fender	92.1	89	99	89
5	Left Front Door	94.2	92	99	92
6	Center Panel Left	70.5	64	74	74
7	Left Rear Door	49.0	56	49	42
8	Left Back Panel	58.6	69	54	53
9	Right Front Fender	92.6	92	94	93
10	Right Front Door	88.3	83	90	93
11	Center Panel Right	99.2	100	103	95
12	Right Rear Door	42.0	43	43	41
13	Right Back Panel	46.4	45	41	53

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">E</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> (R) Front Seat - Grime - Large / Ceiling - Grime - Small / Dashboard - Traces of Adhesive Tape - Yes / (L) Front Floor Mat - Grime - Small</p>	<p><b>Remarks</b> Cargo Bed Floor - Scratch - Large / Rear Gate - Scratch - Large / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Guard Frame - Scratch - Medium / (R) Guard Frame - Scratch - Medium / Cab Back Panel - Scratch - Medium / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch &amp; Dent - Small / Front Bumper, Grille, Lamps - Scratch - Medium / (L) Front Fender, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / Roof - Scratch - Small</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">B</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>with LTO plate/with spare tire/No spare key/No seat cover/No warranty booklet/with jack and tools/No reverse camera/No fog light interior dirty.</p>