

## General Information

Date & Time: 27, Jan, 2026 16:42

<b>Make</b>	Toyota	<b>Model</b>	Wigo
<b>YOM</b>	2023	<b>Odo Meter Reading</b>	54,780
<b>Registration No.</b>	HAG6869	<b>Chassis No.</b>	MHKAA1BC8PJ004094
<b>CC</b>	1.0	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Hatchback
<b>Colour</b>	Red		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	115.6	113	122	112
2	Boot Lid	91.9	81	98	97
3	Roof	84.6	70	87	94/88
4	Left Front Fender	90.9	90	94	89
5	Left Front Door	110.0	101	111	118
6	Center Panel Left				
7	Left Rear Door	98.2	109	96	89
8	Left Back Panel	92.6	97	90	91
9	Right Front Fender	92.9	100	95	84
10	Right Front Door	111.0	119	108	106
11	Center Panel Right				
12	Right Rear Door	102.6	90	106	112
13	Right Back Panel	94.0	100	91	91

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="color: red; font-weight: bold; font-size: 1.2em;">C</span>	<b>Exterior Evaluation :</b> <span style="color: red; font-weight: bold; font-size: 1.2em;">E</span>
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b>  (R) Front Seat - Grime - Large / (R) Front Floor Mat - Grime - Large / Mat Other - Grime - Medium / (L) Front Floor Mat - Worked - Small / Ceiling - Grime - Small</p>	<p><b>Remarks</b>  (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch &amp; Dent - Large / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Large / (L) Front Door, Molding - Scratch - Large / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Scratch - Medium / Roof - Scratch - Small / Bonnet, Headlight - Scratch - Small / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Large / Member (Bolted) - Dent - Yes</p>
<b>Frame Evaluation :</b> <span style="color: red; font-weight: bold; font-size: 1.2em;">A</span>	<b>Functional Evaluation :</b> <span style="color: red; font-weight: bold; font-size: 1.2em;">A</span>
<p><b>Remarks</b>  Defects not found</p>	<p><b>Remarks</b>  Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>Trunk floor missing. Without warranty booklet, jack and tools. Incomplete seat cover. With spare tire. 1 key. With LTO plate.</p>