

## General Information

Date & Time: 11, Feb, 2026 07:39

<b>Make</b>	Toyota	<b>Model</b>	Hilux
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	52,487
<b>Registration No.</b>	DBR5060	<b>Chassis No.</b>	MR0AB8DD3R5154519
<b>CC</b>	2.4	<b>Transmission</b>	A/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	Pickup
<b>Colour</b>	Red		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	124.6	120	124	130
2	Boot Lid	103.5	107	94	110
3	Roof	121.7	128	126	107/126
4	Left Front Fender	117.0	119	114	118
5	Left Front Door	120.6	129	117	116
6	Center Panel Left				
7	Left Rear Door	115.0	123	116	106
8	Left Back Panel	116.0	120	129	99
9	Right Front Fender	112.3	109	113	115
10	Right Front Door	116.6	117	114	119
11	Center Panel Right				
12	Right Rear Door	108.0	114	102	108
13	Right Back Panel	115.0	106	125	114

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right;"><b>B</b></span>	<b>Exterior Evaluation :</b> <span style="float: right;"><b>E</b></span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> (R) Front Seat - Grime - Minimal / (R) Front Floor Mat - Grime - Medium / (L) Front Floor Mat - Missing - Yes / Mat Other - Grime - Small / Ceiling - Grime - Small / Sunvisor, Sunglass Holder - Cut, Crack - Small</p>	<p><b>Remarks</b> (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch &amp; Dent - Small / (R) Rear Door, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Side Gate - Scratch &amp; Dent - Medium / Rear Bumper, Lamps, Panels - Scratch &amp; Dent - Medium / Rear Gate - Scratch &amp; Dent - Large / (L) Side Gate - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch &amp; Dent - Medium / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Medium / Roof - Scratch - Small / Cab Back Panel - Scratch - Medium / Cargo Bed Floor - Scratch - Small / Bonnet, Headlight - Scratch &amp; Dent - Medium / (R) Mirror - Scratch - Minimal</p>
<b>Frame Evaluation :</b> <span style="float: right;"><b>A</b></span>	<b>Functional Evaluation :</b> <span style="float: right;"><b>B</b></span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Battery - Weak - Yes / Remote Key &amp; Smart entry - Issue - Yes</p>

<p><b>Inspector Notes</b></p>
<p>with warranty booklet, jack and tools, spare tire, LTO PLATE, scratches on tail light.</p>