

## General Information

Date & Time: 06, Feb, 2026 12:44

<b>Make</b>	Toyota	<b>Model</b>	Yaris Cross
<b>YOM</b>	2024	<b>Odo Meter Reading</b>	21,747
<b>Registration No.</b>	NOW6706	<b>Chassis No.</b>	MHFAB8BF5R0016677
<b>CC</b>	1.5	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Hybrid	<b>Type of Body</b>	SUV
<b>Colour</b>	Black		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	157.3	160	154	158
2	Boot Lid	145.0	137	157	141
3	Roof	144.5	163	171	127/117
4	Left Front Fender	152.0	159	145	152
5	Left Front Door	151.3	141	150	163
6	Center Panel Left				
7	Left Rear Door	149.0	153	143	151
8	Left Back Panel	160.0	153	168	159
9	Right Front Fender	157.6	148	161	164
10	Right Front Door	158.6	160	154	162
11	Center Panel Right				
12	Right Rear Door	153.0	167	150	142
13	Right Back Panel	161.3	167	164	153

## Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">B</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">D</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> (L) Front Floor Mat - Missing - Yes / (R) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / (L) Front Seat - Worn - Yes / Sunvisor, Sunglass Holder - Grime - Medium / Rear Seat - Grime - Small / (R) Front Seat - Grime - Medium</p>	<p><b>Remarks</b> (R) Mirror - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch &amp; Dent - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch &amp; Dent - Small / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Scratch - Medium / (L) Mirror - Scratch - Small / Roof - Scratch &amp; Dent - Small</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>with warranty booklet, no jack, incomplete tools, with spare tire, with LTO plate but not attached, scratches on tail light</p>