

## General Information

Date & Time: 27, Jan, 2026 17:55

<b>Make</b>	Toyota	<b>Model</b>	Hilux Tamaraw
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	4,145
<b>Registration No.</b>	GBK4605	<b>Chassis No.</b>	PAHACACA6S6426142
<b>CC</b>	2.4	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	Pickup
<b>Colour</b>	White		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	110.3	110	113	108
2	Boot Lid	68.8	64	64	79
3	Roof	108.0	112	105	104/111
4	Left Front Fender	101.2	104	102	98
5	Left Front Door	103.0	102	106	101
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	66.5	67	75	58
9	Right Front Fender	102.1	97	103	106
10	Right Front Door	101.6	100	100	105
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	81.6	78	86	80

## Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">D</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> (L) Front Floor Mat - Worked - Small / Ceiling - Grime - Small / (R) Front Floor Mat - Grime - Small</p>	<p><b>Remarks</b> (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Small / Roof - Scratch &amp; Dent - Medium / (L) Side Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch &amp; Dent - Medium / Rear Gate - Scratch - Small / (R) Side Gate - Scratch - Medium / (R) Front Door, Molding - Scratch - Medium / (R) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small / Bonnet, Headlight - Scratch - Small / (L) Front Fender, Molding - Repair mark - Yes</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Reverse Camera - N/A - Yes</p>

<p><b>Inspector Notes</b></p>
<p>Without jack and tools. With warranty booklet and spare tire. 2 keys. No LTO plate.</p>