

## General Information

Date & Time: 26, Jan, 2026 18:35

<b>Make</b>	Toyota	<b>Model</b>	Hilux Tamaraw
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	9,003
<b>Registration No.</b>	NKQ8944	<b>Chassis No.</b>	PAHACACA1S6425061
<b>CC</b>	2.4	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	Utility Vehicle
<b>Colour</b>	White		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	99.0	101	93	103
2	Boot Lid	44.6	45	42	47
3	Roof	111.5	119	116	105/106
4	Left Front Fender	94.2	92	99	92
5	Left Front Door	94.2	92	94	97
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	76.4	65	95	69
9	Right Front Fender	97.8	107	97	90
10	Right Front Door	95.0	90	100	95
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	73.7	66	78	78

## Overall Evaluation :

**A**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="color: red; font-size: 1.5em; font-weight: bold;">A</span>	<b>Exterior Evaluation :</b> <span style="color: red; font-size: 1.5em; font-weight: bold;">B</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<b>Remarks</b> Defects not found	<b>Remarks</b> (R) Mirror - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / Roof - Scratch - Small / (R) Side Gate - Scratch - Small / (L) Side Gate - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / Bonnet, Headlight - Scratch - Minimal
<b>Frame Evaluation :</b> <span style="color: red; font-size: 1.5em; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="color: red; font-size: 1.5em; font-weight: bold;">A</span>
<b>Remarks</b> Defects not found	<b>Remarks</b> Reverse Camera - N/A - Yes

<b>Inspector Notes</b>
With Lto plate, with warranty booklet, with spare tire and jack, 2keys, no tools, scratches on headlights and taillights