

## General Information

Date & Time: 30, Jan, 2026 11:30

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	9,721
<b>Registration No.</b>	NJC9137	<b>Chassis No.</b>	PA1B18F39S4290969
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Black		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	113.6	118	107	116
2	Boot Lid	110.3	112	109	110
3	Roof	99.1	101	99	97/100
4	Left Front Fender	107.3	107	111	104
5	Left Front Door	100.3	103	97	101
6	Center Panel Left				
7	Left Rear Door	104.0	108	104	100
8	Left Back Panel	104.8	110	105	100
9	Right Front Fender	109.0	105	105	117
10	Right Front Door	102.8	104	105	100
11	Center Panel Right				
12	Right Rear Door	98.3	94	96	105
13	Right Back Panel	100.0	102	98	100

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right;"><b>B</b></span>	<b>Exterior Evaluation :</b> <span style="float: right;"><b>E</b></span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<b>Remarks</b> (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes	<b>Remarks</b> (L) Front Fender - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (L) Rear Door - Repair Traces - Yes / (R) Front Fender, Molding - Scratch & Dent - Large / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Repair mark - Difference in Color / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Repair mark - Yes / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / Trunk Hood, Rear Gate - Repair mark - Yes / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch & Dent - Medium / (L) Rear Door, Molding - Repair mark - Difference in Color / (L) Rear Door, Molding - Scratch & Dent - Medium / (L) Front Door, Molding - Repair mark - Difference in Color / (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Large / (L) Front Fender, Molding - Repair mark - Difference in Color / (L) Front Fender, Molding - Scratch - Large / Roof - Scratch - Small / Bonnet, Headlight - Repair mark - Difference in Color / Bonnet, Headlight - Scratch - Large / Front Bumper, Grille, Lamps - Crack, Gap - Large
<b>Frame Evaluation :</b> <span style="float: right;"><b>A</b></span>	<b>Functional Evaluation :</b> <span style="float: right;"><b>B</b></span>
<b>Remarks</b> Defects not found	<b>Remarks</b> Battery - Weak - Yes / Spare Key - Issue - Unexist

<b>Inspector Notes</b>
No Lto plate, with warranty booklet, with spare tire, 1key, no spare tire and tools, scratches on headlights and taillights, splash of paint on vehicle, battery weak,steering issue