

General Information

Date & Time: 29, Jan, 2026 06:04

Make	Suzuki	Model	Ertiga
YOM	2023	Odo Meter Reading	32,541
Registration No.	GNW1523	Chassis No.	MHYNC32S5RJ100207
CC	1.5	Transmission	A/T
Fuel Type	Gas	Type of Body	Wagon
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	86.5	85	83	92
2	Boot Lid	77.3	76	83	73
3	Roof	112.9	72	82	188/110
4	Left Front Fender	88.3	102	83	80
5	Left Front Door	89.4	90	85	93
6	Center Panel Left				
7	Left Rear Door	88.8	94	86	87
8	Left Back Panel	84.2	83	89	81
9	Right Front Fender	77.3	77	79	77
10	Right Front Door	90.2	88	88	94
11	Center Panel Right				
12	Right Rear Door	90.2	83	86	101
13	Right Back Panel	79.6	82	79	78

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Rear Trim - Grime - Medium / (L) Front Seat - Worn - Yes / (R) Front Seat - Grime - Medium / (R) Front Trim - Grime - Small / Rear Seat - Grime - Large / Trunk Room - Worked - Minimal</p>	<p>Remarks Roof - Repair Traces - Yes / (R) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>With spare tire/No warranty booklet/ No spare key / No Seat cover/ No jack and tools/ with reverse camera</p>