

## General Information

Date & Time: 05, Feb, 2026 10:31

<b>Make</b>	Toyota	<b>Model</b>	Lite Ace
<b>YOM</b>	2023	<b>Odo Meter Reading</b>	15,573
<b>Registration No.</b>	EAG2133	<b>Chassis No.</b>	MHKU3FE10NK002659
<b>CC</b>	1.5	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Utility Vehicle
<b>Colour</b>	White		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	60.7	58	64	59
2	Boot Lid	90.8	108	88	77
3	Roof	62.8	57	66	74/55
4	Left Front Fender	63.4	60	62	69
5	Left Front Door	74.4	76	86	62
6	Center Panel Left	76.3	103	69	57
7	Left Rear Door				
8	Left Back Panel	81.8	97	81	68
9	Right Front Fender	62.2	65	65	57
10	Right Front Door	58.1	54	57	63
11	Center Panel Right	67.8	72	66	66
12	Right Rear Door				
13	Right Back Panel	88.4	79	94	93

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">B</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">D</span>
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b>  (R) Front Floor Mat - Cut, Crack - Medium / (L) Front Seat - Grime - Minimal / (L) Front Floor Mat - Worked - Small / (R) Front Seat - Grime - Small / (L) Front Trim - Grime - Small / (R) Front Trim - Grime - Small / Rear Seat - Grime - Small / Dashboard - Worked - Minimal / Ceiling - Grime - Minimal</p>	<p><b>Remarks</b>  (L) Center Panel - Scratch &amp; Dent - Minimal / (L) Front Door, Molding - Scratch &amp; Dent - Small / (L) Front Fender, Molding - Scratch &amp; Dent - Small / Front Panel - Scratch &amp; Dent - Small / (R) Front Fender, Molding - Scratch &amp; Dent - Small / (R) Front Door, Molding - Scratch &amp; Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch &amp; Dent - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Side Gate - Scratch &amp; Dent - Medium / Rear Gate - Scratch &amp; Dent - Medium / (L) Side Gate - Scratch &amp; Dent - Medium / Rear Bumper, Lamps, Panels - Scratch &amp; Dent - Small / Roof - Scratch &amp; Dent - Small / Cab Back Panel - Scratch &amp; Dent - Small</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">B</span>
<p><b>Remarks</b>  Defects not found</p>	<p><b>Remarks</b>  Battery - Weak - Yes / Reverse Camera - N/A - Yes</p>

<p><b>Inspector Notes</b></p>
<p>with LTO plate, with spare tire, with incomplete tools and jack, with spare key, with manual and warranty booklet, tailight and headlight,</p>