

General Information

Date & Time: 04, Feb, 2026 08:17

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	116,005
Registration No.	NIG7473	Chassis No.	PA1B18F32N4199305
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	102.3	104	99	104
2	Boot Lid	196.6	214	224	152
3	Roof	91.6	94	96	81/96
4	Left Front Fender	320.6	147	638	177
5	Left Front Door	97.7	103	93	97
6	Center Panel Left				
7	Left Rear Door	98.7	101	95	100
8	Left Back Panel	107.8	119	108	96
9	Right Front Fender	97.7	100	94	99
10	Right Front Door	106.2	93	95	131
11	Center Panel Right				
12	Right Rear Door	94.5	100	89	94
13	Right Back Panel	97.8	90	91	113

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Seat - Grime - Medium / (R) Front Trim - Grime - Small / Rear Seat - Grime - Medium / (L) Front Trim - Grime - Medium / (L) Front Seat - Grime - Medium / (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / Trunk Room - Worn, Scratch, Cut, Crack - Small / Sunvisor, Sunglass Holder - Missing - Yes / Room Mirror - Missing - Yes / Dashboard - Worn, Scratch, Cut, Crack - Small</p>	<p>Remarks (L) Front Fender - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / Roof - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (L) Front Fender, Molding - Repair mark - Yes / Trunk Hood, Rear Gate - Repair mark - Yes / (R) Front Fender, Molding - Scratch & Dent - Medium / Bonnet, Headlight - Scratch - Medium / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Large / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch & Dent - Medium / (L) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Large / (R) Rear Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (R) Front Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / (R) Mirror - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Head Light, High Beam - Issue - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with LTO plate/with spare tire/No spare key/No jack and tools/No reverse camera/with warranty booklet/headlights issue/plate light issue/rear view mirror missing/sun visor missing/front and back floor mats missing/No seat cover</p>