

General Information

Date & Time: 02, Feb, 2025 14:07

Make	Toyota	Model	Vios
YOM	2021	Mileage	55,782
Registration No.	CBL6814	Chassis No.	PA1B18F34M4134468
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	111.6	109	116	110
2	Boot Lid	106.0	107	105	106
3	Roof	99.1	109	98	90/100
4	Left Front Fender	98.4	108	100	87
5	Left Front Door	99.5	98	104	96
6	Center Panel Left				
7	Left Rear Door	95.9	106	94	88
8	Left Back Panel	114.6	113	114	117
9	Right Front Fender	97.6	94	98	101
10	Right Front Door	103.5	112	100	99
11	Center Panel Right				
12	Right Rear Door	100.3	98	97	106
13	Right Back Panel	103.9	97	100	115

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Small / (L) Front Floor Mat - Worked - Large / Overall Interior - Smell - Yes / (R) Front Floor Mat - Worked - Small	Remarks Front Bumper, Grille, Lamps - Scratch - Medium / (L) Rear Fender, Molding - Scratch & Dent - Minimal / Trunk Hood, Rear Gate - Dent - Minimal / (R) Rear Fender, Molding - Scratch & Dent - Medium / (R) Front Door, Molding - Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / Roof - Dent - Small / (L) Rear Door, Molding - Dent - Minimal / (L) Front Door, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes
no tools/ missing trunk carpet/ with spare tire and jack/ with warranty booklet/ with LTO plate