

General Information

Date & Time: 10, Feb, 2026 13:16

Make	Suzuki	Model	XL7
YOM	2025	Odo Meter Reading	12,776
Registration No.	GBK9480	Chassis No.	MHYNC32S8TJ100211
CC	1.5	Transmission	A/T
Fuel Type	Gas	Type of Body	Wagon
Colour	Orange		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	153.3	180	121	159
2	Boot Lid	107.3	152	75	95
3	Roof	83.0	73	85	85/90
4	Left Front Fender	145.0	141	139	155
5	Left Front Door	145.3	145	137	154
6	Center Panel Left				
7	Left Rear Door	146.3	153	143	143
8	Left Back Panel	133.3	138	131	131
9	Right Front Fender	154.6	164	150	150
10	Right Front Door	160.0	162	165	153
11	Center Panel Right				
12	Right Rear Door	151.6	149	144	162
13	Right Back Panel	152.0	158	148	150

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	B	Exterior Evaluation :	B
			
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks (R) Front Seat - Grime - Small / Rear Seat - Grime - Medium / (R) Front Trim - Grime - Small / Dashboard - Worn, Scratch, Cut, Crack - Minimal</p>		<p>Remarks Trunk Hood, Rear Gate - Repair Traces - Yes / Roof - Repair Traces - Yes / (R) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Dent - Small / (R) Front Door, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch & Dent - Small</p>	
Frame Evaluation :	A	Functional Evaluation :	A
<p>Remarks Defects not found</p>		<p>Remarks Defects not found</p>	

Inspector Notes
with spare key. with spare tire. with jack and tools. with warranty booklet.no seat cover.