

## General Information

Date & Time: 11, Feb, 2026 15:13

<b>Make</b>	Honda	<b>Model</b>	City
<b>YOM</b>	2022	<b>Odo Meter Reading</b>	47,815
<b>Registration No.</b>	NFP2147	<b>Chassis No.</b>	MRHGN2620NT061353
<b>CC</b>	1.5	<b>Transmission</b>	A/T
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Red		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	252.0	136	473	147
2	Boot Lid	137.6	115	153	145
3	Roof	135.0	121	164	135/120
4	Left Front Fender	159.0	145	147	185
5	Left Front Door	179.0	222	142	173
6	Center Panel Left				
7	Left Rear Door	170.0	154	158	198
8	Left Back Panel	186.0	194	186	178
9	Right Front Fender	168.0	193	174	137
10	Right Front Door	164.0	185	135	172
11	Center Panel Right				
12	Right Rear Door	194.0	242	162	178
13	Right Back Panel	155.0	148	144	173

Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b>	<b>C</b>	<b>Exterior Evaluation :</b>	<b>E</b>
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>		<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>	
<b>Remarks</b>		<b>Remarks</b>	
<p>(R) Front Seat - Grime - Medium / (L) Front Floor Mat - Grime - Medium / (R) Front Floor Mat - Grime - Medium / (L) Front Seat - Cigarette Burns - Burnt Minimal / (L) Front Trim - Grime - Small / (R) Front Trim - Grime - Small / (L) Rear Trim - Grime - Minimal / (R) Rear Trim - Grime - Minimal / Glove Box - Worked - Minimal / Ceiling - Grime - Minimal / Rear Seat - Grime - Small</p>		<p>(R) Step - Repair Traces - Yes / (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (L) Step - Repair Traces - Yes / (L) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / Overall Exterior - Full Re-Paint in same color - Yes / Roof - Scratch &amp; Dent - Small / (L) Rear Door, Molding - Scratch &amp; Dent - Small / (L) Front Door, Molding - Scratch &amp; Dent - Small / (L) Step, In-panel, Side Spoiler - Scratch &amp; Dent - Medium / (L) Front Fender, Molding - Scratch &amp; Dent - Small / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Front Fender, Molding - Scratch &amp; Dent - Small / (R) Front Door, Molding - Scratch &amp; Dent - Small / (R) Rear Door, Molding - Scratch &amp; Dent - Medium / (R) Step, In-panel, Side Spoiler - Scratch &amp; Dent - Small / (R) Rear Fender, Molding - Scratch &amp; Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Rear Fender, Molding - Scratch &amp; Dent - Small / Trunk Hood, Rear Gate - Scratch &amp; Dent - Small / Bonnet, Headlight - Scratch &amp; Dent - Small</p>	
<b>Frame Evaluation :</b>	<b>A</b>	<b>Functional Evaluation :</b>	<b>A</b>
<b>Remarks</b>		<b>Remarks</b>	
<p>Defects not found</p>		<p>Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>	

<b>Inspector Notes</b>
<p>No LTO plate, with spare tire, with jack, with manual and warranty booklet, no spare key, no tools, no reverse camera, scratches on taillight and headlight</p>