

## General Information

Date & Time: 14, Feb, 2026 16:03

<b>Make</b>	Toyota	<b>Model</b>	Hilux Tamaraw
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	35,138
<b>Registration No.</b>	CCG7962	<b>Chassis No.</b>	PAHACACA8R542038
<b>CC</b>	2.4	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	Utility Vehicle
<b>Colour</b>	White		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	99.4	101	95	102
2	Boot Lid	69.6	67	71	71
3	Roof	166.7	180	187	186/114
4	Left Front Fender	124.0	154	116	102
5	Left Front Door	94.3	89	94	100
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	55.8	44	64	59
9	Right Front Fender	99.2	91	108	99
10	Right Front Door	94.1	94	95	94
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	99.7	94	97	108

## Overall Evaluation :

C

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right;"><b>B</b></span>	<b>Exterior Evaluation :</b> <span style="float: right;"><b>E</b></span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> (L) Front Floor Mat - Grime - Medium / (R) Front Floor Mat - Grime - Small / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small / Rear Seat - Grime - Small / (L) Front Trim - Grime - Minimal / (R) Front Trim - Grime - Minimal / Ceiling - Grime - Small</p>	<p><b>Remarks</b> Roof - Repair Traces - Yes / Rear Bumper, Lamps, Panels - Scratch &amp; Dent - Small / (L) Side Gate - Scratch - Medium / (L) Guard Frame - Scratch &amp; Dent - Large / (L) Front Door, Molding - Scratch &amp; Dent - Small / (L) Front Fender, Molding - Scratch &amp; Dent - Small / Bonnet, Headlight - Scratch &amp; Dent - Small / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Small / (R) Front Fender, Molding - Scratch &amp; Dent - Small / Roof - Scratch &amp; Dent - Small / (R) Front Door, Molding - Scratch &amp; Dent - Small / (R) Guard Frame - Scratch &amp; Dent - Small / (R) Side Gate - Scratch &amp; Dent - Medium / Rear Gate - Scratch &amp; Dent - Small / Cargo Bed Floor - Scratch &amp; Dent - Medium</p>
<b>Frame Evaluation :</b> <span style="float: right;"><b>A</b></span>	<b>Functional Evaluation :</b> <span style="float: right;"><b>B</b></span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Battery - Weak - Yes / Reverse Camera - N/A - Yes / Turn Signal, Hazard Flasher - Issue - Yes</p>

<p><b>Inspector Notes</b></p>
<p>with LTO plate, with jack, with spare tire, with spare key, no reverse camera, scratches on taillight and headlight.</p>