

## General Information

Date & Time: 12, Feb, 2026 19:00

<b>Make</b>	Toyota	<b>Model</b>	Wigo
<b>YOM</b>	2021	<b>Odo Meter Reading</b>	22,798
<b>Registration No.</b>	DBF1681	<b>Chassis No.</b>	MHKA4DF5FMJ057937
<b>CC</b>	1.0	<b>Transmission</b>	A/T
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Hatchback
<b>Colour</b>	Black		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	90.8	84	94	94
2	Boot Lid	105.1	96	118	101
3	Roof	73.6	71	71	76/77
4	Left Front Fender	98.1	94	97	103
5	Left Front Door	102.8	102	109	98
6	Center Panel Left				
7	Left Rear Door	104.0	104	104	104
8	Left Back Panel	96.6	100	100	90
9	Right Front Fender	104.7	113	105	96
10	Right Front Door	101.4	95	104	105
11	Center Panel Right				
12	Right Rear Door	102.0	110	98	98
13	Right Back Panel	105.6	101	106	110

## Overall Evaluation :

**A**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="color: red; font-size: 24px; float: right;">A</span>	<b>Exterior Evaluation :</b> <span style="color: red; font-size: 24px; float: right;">C</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> Dashboard - Traces of Adhesive Tape - Yes</p>	<p><b>Remarks</b> (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Front Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Medium / Roof - Scratch - Minimal / Bonnet, Headlight - Scratch - Medium</p>
<b>Frame Evaluation :</b> <span style="color: red; font-size: 24px; float: right;">A</span>	<b>Functional Evaluation :</b> <span style="color: red; font-size: 24px; float: right;">A</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>With Lto plate, with warranty booklet, with spare tire, 1key, no jack and tools, scratches on headlights and taillights</p>