

General Information

Date & Time: 02, Feb, 2025 11:03

Make	Toyota	Model	Wigo
YOM	2023	Mileage	47,610
Registration No.	EAJ3277	Chassis No.	MHKAA1BC5PJ003307
CC	1.0	Transmission	CVT
Fuel Type	Gas	Type of Body	Hatchback
Colour	Yellow		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	109.3	105	115	108
2	Boot Lid	103.2	94	108	108
3	Roof	92.4	81	100	100/90
4	Left Front Fender	101.0	105	97	101
5	Left Front Door	103.7	96	98	117
6	Center Panel Left				
7	Left Rear Door	100.7	111	102	89
8	Left Back Panel	97.8	93	95	106
9	Right Front Fender	97.6	103	105	85
10	Right Front Door	105.4	113	105	98
11	Center Panel Right				
12	Right Rear Door	102.9	98	101	110
13	Right Back Panel	95.0	99	91	96

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Large / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Medium / Steering Wheel - Worn, Peel, Crack - Small	Remarks Front Bumper, Grille, Lamps - Scratch - Large / (R) Front Door, Molding - Scratch & Dent - Medium / (L) Front Fender, Molding - Scratch - Medium / Roof - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

right front mud flaps torn/ no warranty booklet/ reverse camera issue/ with spare tire and tools/ with jack