

## General Information

Date & Time: 16, Feb, 2026 08:26

<b>Make</b>	Toyota	<b>Model</b>	Hilux Tamaraw
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	3,883
<b>Registration No.</b>	HAH9854	<b>Chassis No.</b>	PAHAWAAA4S1340271
<b>CC</b>	2.0	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Pickup
<b>Colour</b>	White		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	104.3	107	104	102
2	Boot Lid	57.6	62	54	57
3	Roof	112.0	117	120	108/103
4	Left Front Fender	96.5	96	101	93
5	Left Front Door	101.3	102	102	100
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	84.5	95	86	73
9	Right Front Fender	97.3	96	101	95
10	Right Front Door	97.5	94	99	99
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	62.3	57	63	67

## Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">B</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> Ceiling - Grime - Small / (L) Front Floor Mat - Worked - Small / (L) Front Seat - Grime - Medium / (R) Front Seat - Grime - Medium / (R) Front Floor Mat - Grime - Small</p>	<p><b>Remarks</b> (R) Mirror - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Side Gate - Scratch &amp; Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Rear Gate - Scratch &amp; Dent - Large / (L) Side Gate - Scratch - Small / Cab Back Panel - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Large / (R) Front Fender, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Small</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>Scratches on headlight and taillight. Crack on right headlight. Without warranty booklet, jack and tools. With spare tire. 1 key. With LTO plate.</p>