

## General Information

Date & Time: 16, Feb, 2026 15:10

<b>Make</b>	Toyota	<b>Model</b>	Wigo
<b>YOM</b>	2023	<b>Odo Meter Reading</b>	44,954
<b>Registration No.</b>	DBG2632	<b>Chassis No.</b>	MHKA4DF5FNJ076071
<b>CC</b>	1.0	<b>Transmission</b>	A/T
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Hatchback
<b>Colour</b>	Gray		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	122.3	107	104	156
2	Boot Lid	104.7	94	110	110
3	Roof	96.8	96	99	99/95
4	Left Front Fender	108.6	100	115	111
5	Left Front Door	99.2	98	105	95
6	Center Panel Left				
7	Left Rear Door	111.3	100	131	103
8	Left Back Panel	110.6	113	117	102
9	Right Front Fender	95.3	98	108	80
10	Right Front Door	102.3	98	103	106
11	Center Panel Right				
12	Right Rear Door	101.3	111	103	90
13	Right Back Panel	108.3	113	104	108

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b>	C	<b>Exterior Evaluation :</b>	E
			
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>		<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>	
<p><b>Remarks</b> Trunk Room - Loose, Deformed - Medium / (L) Front Trim - Worked - Small / (R) Front Trim - Worked - Small / (R) Rear Trim - Worked - Small / Rear Seat - Grime - Small / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small / Ceiling - Grime - Medium</p>		<p><b>Remarks</b> (R) Front Fender - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / Roof - Scratch &amp; Dent - Small / (L) Front Door, Molding - Scratch &amp; Dent - Medium / (L) Rear Door, Molding - Scratch &amp; Dent - Medium / (L) Step, In-panel, Side Spoiler - Scratch &amp; Dent - Medium / (L) Rear Fender, Molding - Scratch &amp; Dent - Medium / Rear Bumper, Lamps, Panels - Crack, Gap - Medium / (R) Rear Fender, Molding - Scratch &amp; Dent - Small / (R) Rear Door, Molding - Scratch &amp; Dent - Medium / (R) Step, In-panel, Side Spoiler - Scratch &amp; Dent - Medium / (R) Front Door, Molding - Scratch &amp; Dent - Small / (R) Front Fender, Molding - Scratch &amp; Dent - Medium / Bonnet, Headlight - Scratch &amp; Dent - Small / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Medium</p>	
<b>Frame Evaluation :</b>	A	<b>Functional Evaluation :</b>	A
<p><b>Remarks</b> Defects not found</p>		<p><b>Remarks</b> Spare Key - Issue - Unexist</p>	

<b>Inspector Notes</b>
with LTO plate, with warranty and manual booklet, with reverse camera, with spare tire, no spare key, no tools and jack, scratches on taillight and headlight.