

## General Information

Date & Time: 18, Feb, 2026 17:39

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2024	<b>Odo Meter Reading</b>	71,738
<b>Registration No.</b>	DBM7330	<b>Chassis No.</b>	PA1B18F35R4247899
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Black		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	112.0	115	111	110
2	Boot Lid	100.8	100	98	104
3	Roof	99.5	103	104	90/101
4	Left Front Fender	207.0	192	284	145
5	Left Front Door	103.2	103	107	100
6	Center Panel Left				
7	Left Rear Door	100.5	104	102	96
8	Left Back Panel	107.0	114	105	102
9	Right Front Fender	96.4	103	93	93
10	Right Front Door	315.3	694	126	126
11	Center Panel Right				
12	Right Rear Door	102.6	100	101	107
13	Right Back Panel	106.2	108	100	111

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b>	C	<b>Exterior Evaluation :</b>	E
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>		<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>	
<p><b>Remarks</b> Rear Seat - Grime - Large / (R) Front Trim - Grime - Small / (R) Front Seat - Grime - Large / (L) Front Seat - Grime - Large / (L) Front Floor Mat - Worked - Large / (L) Front Trim - Grime - Medium</p>		<p><b>Remarks</b> (R) Front Door - Repair Traces - Yes / (R) Step - Repair Traces - Yes / (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (L) Step - Repair Traces - Yes / Rear Bumper, Lamps, Panels - Scratch - Large / (R) Rear Door, Molding - Scratch &amp; Dent - Large / (R) Front Door, Molding - Scratch &amp; Dent - Large / (R) Front Door, Molding - Repair mark - Yes / (R) Step, In-panel, Side Spoiler - Scratch &amp; Dent - Large / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Large / (R) Front Fender, Molding - Crack, Gap - Medium / Bonnet, Headlight - Repair mark - Yes / (L) Front Fender, Molding - Scratch - Large / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Large / (L) Front Door, Molding - Scratch - Small</p>	
<b>Frame Evaluation :</b>	A	<b>Functional Evaluation :</b>	A
<p><b>Remarks</b> Defects not found</p>		<p><b>Remarks</b> Spare Key - Issue - Unexist</p>	

<b>Inspector Notes</b>
no warranty booklet / no tools/ no jack/ with spare tire and LTO plate/