

General Information

Date & Time: 05, Feb, 2025 17:40

Make	Toyota	Model	Vios
YOM	2022	Mileage	30,317
Registration No.	DAR6206	Chassis No.	PA1B18F35N4183079
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	109.6	112	107	110
2	Boot Lid	106.0	102	105	111
3	Roof	99.4	104	94	102/98
4	Left Front Fender	99.0	96	103	99
5	Left Front Door	99.2	101	100	97
6	Center Panel Left				
7	Left Rear Door	98.1	100	97	98
8	Left Back Panel	108.6	108	110	108
9	Right Front Fender	101.1	98	112	93
10	Right Front Door	99.0	102	104	91
11	Center Panel Right				
12	Right Rear Door	106.0	106	105	107
13	Right Back Panel	104.8	98	105	112

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Medium / (R) Front Seat - Grime - Large / Mat Other - Grime - Medium / (L) Front Floor Mat - Worked - Small / (R) Front Floor Mat - Grime - Small	Remarks (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / Roof - Rust, Corrosion - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes
with warranty booklet, with spare tire, with jack and tools, with LTO plate,