

## General Information

Date & Time: 18, Feb, 2026 16:08

<b>Make</b>	Toyota	<b>Model</b>	Wigo
<b>YOM</b>	2024	<b>Odo Meter Reading</b>	22,111
<b>Registration No.</b>	DBQ2900	<b>Chassis No.</b>	MHKAA1BCXRJ024270
<b>CC</b>	1.0	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Hatchback
<b>Colour</b>	Gray		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	110.9	113	124	96
2	Boot Lid	82.8	82	88	79
3	Roof	73.1	74	75	76/68
4	Left Front Fender	95.7	98	98	91
5	Left Front Door	104.1	96	108	109
6	Center Panel Left				
7	Left Rear Door	101.2	109	97	98
8	Left Back Panel	94.3	97	93	93
9	Right Front Fender	94.1	97	99	86
10	Right Front Door	105.6	113	101	103
11	Center Panel Right				
12	Right Rear Door	98.6	90	95	111
13	Right Back Panel	85.7	91	84	83

## Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="color: red; font-size: 1.5em; vertical-align: middle;">C</span>	<b>Exterior Evaluation :</b> <span style="color: red; font-size: 1.5em; vertical-align: middle;">B</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> Steering Wheel - Worn, Peel, Crack - Large / Console, Switches, Vents - Loose, Deformed - Minimal</p>	<p><b>Remarks</b> (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch &amp; Dent - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Front Fender, Molding - Dent - Small / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Medium / Bonnet, Headlight - Scratch - Minimal</p>
<b>Frame Evaluation :</b> <span style="color: red; font-size: 1.5em; vertical-align: middle;">A</span>	<b>Functional Evaluation :</b> <span style="color: red; font-size: 1.5em; vertical-align: middle;">C</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Warning Lamps - Issue - Yes / Panel, Meter - Issue - Yes / Horn - Issue - Yes / Seat Belts - Issue - Yes</p>

<p><b>Inspector Notes</b></p>
<p>With Lto plate, with warranty booklet, with jack, 2keys, no spare tire and tools, scratches on headlights and taillights, front wiper cowl cover partiality missing, warning lamp on,</p>