

General Information

Date & Time: 21, Feb, 2026 10:04

Make	Ford	Model	Ranger
YOM	2018	Odo Meter Reading	55,628
Registration No.	NAA3555	Chassis No.	MNCLMFF80HW790491
CC	2.2	Transmission	A/T
Fuel Type	Diesel	Type of Body	Pickup
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	174.6	183	169	172
2	Boot Lid	117.0	108	122	121
3	Roof	149.0	147	229	118/102
4	Left Front Fender	131.3	126	120	148
5	Left Front Door	143.0	142	141	146
6	Center Panel Left				
7	Left Rear Door	131.3	144	128	122
8	Left Back Panel	107.8	110	116	98
9	Right Front Fender	367.6	593	349	161
10	Right Front Door	119.0	139	129	89
11	Center Panel Right				
12	Right Rear Door	93.3	94	91	95
13	Right Back Panel	112.7	148	104	86

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Overall Interior - Worn as per age - Yes / (L) Front Seat - Worn - Yes / (R) Front Seat - Worn - Yes / Steering Wheel - Worn, Peel, Crack - Large</p>	<p>Remarks (R) Front Door - Repair Traces - Yes / (R) Step - Repair Traces - Yes / (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Step - Repair Traces - Yes / Roof - Repair Traces - Yes / Bonnet, Headlight - Repair mark - Yes / (R) Side Gate - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Modified - Large / Rear Gate - Scratch & Dent - Medium / (L) Side Gate - Scratch - Large / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Dent - Small / (L) Front Fender, Molding - Scratch - Large / Front Bumper, Grille, Lamps - Crack, Gap - Large / Front Bumper, Grille, Lamps - Repair mark - Yes / (R) Front Fender, Molding - Scratch - Large / (R) Front Fender, Molding - Repair mark - Yes / (R) Front Door, Molding - Repair mark - Yes / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (L) Front Fender, Molding - Repair mark - Yes / Roof - Scratch - Large</p>
Frame Evaluation : C	Functional Evaluation : B
<p>Remarks Front Cross Member Support - Traces of Bending, or Marks of Panel Repair ? - Yes / Rear Frame - Traces of Bending, or Marks of Panel Repair ? - Yes</p>	<p>Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>hood issue/ no warranty booklet/ no jack and tools/ with spare tire/ with LTO plate /</p>