

## General Information

Date & Time: 21, Feb, 2026 16:59

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2023	<b>Odo Meter Reading</b>	31,175
<b>Registration No.</b>	NGC1222	<b>Chassis No.</b>	PA1B18F38P4213503
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Silver		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	167.0	260	101	140
2	Boot Lid	152.0	142	156	158
3	Roof	104.2	104	104	100/109
4	Left Front Fender	470.3	231	471	709
5	Left Front Door	255.3	508	129	129
6	Center Panel Left				
7	Left Rear Door	108.2	119	111	95
8	Left Back Panel	103.7	101	96	114
9	Right Front Fender	96.9	94	96	101
10	Right Front Door	103.0	101	102	106
11	Center Panel Right				
12	Right Rear Door	107.0	105	107	109
13	Right Back Panel	109.6	102	110	117

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b>	A	<b>Exterior Evaluation :</b>	E
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>		<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>	
<p><b>Remarks</b> (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Small / Rear Seat - Cut, Crack - Small</p>		<p><b>Remarks</b> (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (L) Step - Repair Traces - Yes / (L) Rear Door - Repair Traces - Yes / (L) Rear Fender - Repair Traces - Yes / (L) Front Door, Molding - Scratch &amp; Dent - Medium / (L) Rear Fender, Molding - Scratch &amp; Dent - Medium / Trunk Hood, Rear Gate - Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / (R) Rear Fender, Molding - Scratch &amp; Dent - Large / (R) Front Fender, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Crack, Gap - Large / Bonnet, Headlight - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small</p>	
<b>Frame Evaluation :</b>	A	<b>Functional Evaluation :</b>	B
<p><b>Remarks</b> Defects not found</p>		<p><b>Remarks</b> Retractable Mirror - Issue - Yes / Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>	

<b>Inspector Notes</b>
<p>no warranty booklet/ no tools/ with jack and spare tire/ with LTO plate</p>