

General Information

Date & Time: 20, Feb, 2026 13:35

Make	Hyundai	Model	Stargazer
YOM	2024	Odo Meter Reading	47,026
Registration No.	FAQ2625	Chassis No.	MF3NB81DERJ037120
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	MPV
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	132.3	130	123	144
2	Boot Lid	111.6	112	123	100
3	Roof	126.0	132	121	121/130
4	Left Front Fender	105.3	93	111	112
5	Left Front Door	125.3	128	126	122
6	Center Panel Left				
7	Left Rear Door	120.3	117	127	117
8	Left Back Panel	122.0	123	125	118
9	Right Front Fender	114.9	135	110	100
10	Right Front Door	123.3	118	125	127
11	Center Panel Right				
12	Right Rear Door	123.0	119	122	128
13	Right Back Panel	128.6	123	130	133

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Grime - Medium / (L) Front Trim - Grime - Small / Mat Other - Grime - Medium / Ceiling - Grime - Large / (R) Rear Trim - Grime - Small / (R) Front Floor Mat - Grime - Medium / (R) Front Trim - Grime - Small</p>	<p>Remarks (L) Mirror - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch & Dent - Large / Trunk Hood, Rear Gate - Scratch - Large / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch & Dent - Large / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Rear Door, Molding - Scratch - Minimal / (R) Mirror - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch - Medium</p>
Frame Evaluation : A	Functional Evaluation : D
<p>Remarks Defects not found</p>	<p>Remarks Power Window (each) - Stuck, Gap - Yes / Air Conditioner - Function - Weak / Battery - Weak - Yes / Reverse Camera - N/A - Yes</p>

Inspector Notes
Air-conditioning issue. Trunk floor partially missing. Rusted seat railings. Without warranty booklet and tools. With spare tire and jack. 2 keys. With LTO plate.