

## General Information

Date & Time: 20, Feb, 2026 16:05

<b>Make</b>	Mitsubishi	<b>Model</b>	L300
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	1,497
<b>Registration No.</b>	NKP2137	<b>Chassis No.</b>	PAEL65NYSSB002449
<b>CC</b>	2.2	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	FB Body
<b>Colour</b>	White		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	73.3	80	72	69
2	Boot Lid	69.8	70	51	89
3	Roof	65.7	61	67	72/64
4	Left Front Fender	96.9	140	71	80
5	Left Front Door	70.9	73	69	71
6	Center Panel Left	78.7	80	79	78
7	Left Rear Door	77.5	79	81	72
8	Left Back Panel	85.2	79	82	94
9	Right Front Fender	80.6	74	95	73
10	Right Front Door	85.7	68	110	79
11	Center Panel Right	82.8	96	75	78
12	Right Rear Door	85.6	79	85	93
13	Right Back Panel	78.8	90	78	70

## Overall Evaluation :

**A**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right;"><b>B</b></span>	<b>Exterior Evaluation :</b> <span style="float: right;"><b>B</b></span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small / Rear Seat - Grime - Minimal / (L) Front Trim - Grime - Minimal / (R) Front Trim - Grime - Small / Ceiling - Grime - Minimal / (L) Front Floor Mat - Grime - Minimal</p>	<p><b>Remarks</b> (L) Side Gate - Scratch &amp; Dent - Small / (L) Front Door, Molding - Scratch &amp; Dent - Small / (L) Front Fender, Molding - Scratch &amp; Dent - Small / Front Panel - Scratch &amp; Dent - Minimal / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Small / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch &amp; Dent - Minimal / (R) Center Panel - Scratch &amp; Dent - Minimal / Roof - Scratch &amp; Dent - Small / (R) Side Gate - Scratch &amp; Dent - Small / Rear Gate - Scratch &amp; Dent - Small</p>
<b>Frame Evaluation :</b> <span style="float: right;"><b>A</b></span>	<b>Functional Evaluation :</b> <span style="float: right;"><b>A</b></span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Reverse Camera - N/A - Yes</p>

<p><b>Inspector Notes</b></p>
<p>with LTO plate, with warranty booklet ,with jack,with spare key,with spare tire, scratches on taillight and headlight,</p>