

General Information

Date & Time: 21, Feb, 2026 19:23

Make	Toyota	Model	Avanza
YOM	2024	Odo Meter Reading	52,891
Registration No.	CCC9018	Chassis No.	MHFAB1BY2R3097385
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	Wagon
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	206.0	204	208	206
2	Boot Lid	96.5	99	102	89
3	Roof	110.5	121	125	100/96
4	Left Front Fender	127.3	138	125	119
5	Left Front Door	112.3	109	113	115
6	Center Panel Left				
7	Left Rear Door	169.0	177	158	172
8	Left Back Panel	103.0	111	107	91
9	Right Front Fender	103.0	111	98	100
10	Right Front Door	169.6	201	149	159
11	Center Panel Right				
12	Right Rear Door	108.3	109	104	112
13	Right Back Panel	105.3	102	101	113

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Rear Seat - Grime - Large / (L) Front Seat - Grime - Medium / (R) Front Seat - Grime - Small / Overall Interior - Smell - Yes</p>	<p>Remarks (R) Front Door - Repair Traces - Yes / (R) Step - Repair Traces - Yes / (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Step - Repair Traces - Yes / (L) Rear Door - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Rear Door, Molding - Repair mark - Yes / (L) Rear Fender, Molding - Scratch & Dent - Large / (L) Rear Door, Molding - Dent - Large / (L) Step, In-panel, Side Spoiler - Repair mark - Yes / (L) Step, In-panel, Side Spoiler - Dent - Small / (L) Front Door, Molding - Repair mark - Yes / (L) Center Panel - Repair mark - Yes / (L) Rear Door, Molding - Repair mark - Yes / (L) Rear Fender, Molding - Repair mark - Yes / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Repair mark - Yes / Trunk Hood, Rear Gate - Crack, Gap - Large / (R) Rear Fender, Molding - Repair mark - Yes / (R) Front Door, Molding - Repair mark - Yes / Front Bumper, Grille, Lamps - Repair mark - Yes / (R) Rear Fender, Molding - Crack, Gap - Large / (R) Rear Door, Molding - Scratch - Large / (R) Front Fender, Molding - Repair mark - Yes / Front Bumper, Grille, Lamps - Crack, Gap - Large</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>no jack and tools/ with spare tire and LTO plate/ with warranty booklet/</p>