

General Information

Date & Time: 02, Feb, 2025 09:38

Make	Toyota	Model	Vios
YOM	2022	Mileage	53,476
Registration No.	DAP5981	Chassis No.	PA1B18F30N4169820
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Green		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	102.0	106	99	101
2	Boot Lid	104.6	104	105	105
3	Roof	94.4	102	91	87/98
4	Left Front Fender	98.0	100	99	96
5	Left Front Door	91.5	92	89	93
6	Center Panel Left				
7	Left Rear Door	98.1	98	102	94
8	Left Back Panel	100.2	101	101	99
9	Right Front Fender	83.4	80	82	88
10	Right Front Door	143.0	140	140	149
11	Center Panel Right				
12	Right Rear Door	154.3	150	140	173
13	Right Back Panel	212.6	163	166	309

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Cut, Crack - Small / Rear Seat - Grime - Small / (L) Front Seat - Cut, Crack - Medium	Remarks (R) Front Door - Repair Traces - Yes / (R) Front Fender - Repair Traces - Yes / Bonnet - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / Front Bumper, Grille, Lamps - Scratch - Large / (R) Front Fender, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Large / Roof - Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes

no tools/ with jack and spare tire/ with warranty booklet/ worn tires/ with LTO plate