

General Information

Date & Time: 21, Feb, 2026 16:37

Make	Toyota	Model	Fortuner
YOM	2023	Odo Meter Reading	48,848
Registration No.	NIS5240	Chassis No.	MHFBA3FS1P1052598
CC	2.8	Transmission	A/T
Fuel Type	Diesel	Type of Body	SUV
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	128.3	131	125	129
2	Boot Lid	202.6	163	290	155
3	Roof	156.2	156	141	182/146
4	Left Front Fender	183.3	183	179	188
5	Left Front Door	124.3	128	123	122
6	Center Panel Left				
7	Left Rear Door	110.6	111	114	107
8	Left Back Panel	123.0	127	119	123
9	Right Front Fender	117.0	124	115	112
10	Right Front Door	112.3	112	107	118
11	Center Panel Right				
12	Right Rear Door	188.6	182	181	203
13	Right Back Panel	122.6	121	118	129

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	C	Exterior Evaluation :	E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks Rear Seat - Grime - Large / (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small / Dashboard - Traces of Adhesive Tape - Yes</p>		<p>Remarks (R) Step - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (L) Step - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / (L) Front Fender, Molding - Repair mark - Yes / (L) Front Door, Molding - Crack, Gap - Medium / Rear Bumper, Lamps, Panels - Scratch - Large / Trunk Hood, Rear Gate - Repair mark - Yes / Trunk Hood, Rear Gate - Scratch - Small / (R) Rear Fender, Molding - Scratch - Large / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Front Door, Molding - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / Bonnet, Headlight - Dent - Small / Front Bumper, Grille, Lamps - Crack, Gap - Large</p>	
Frame Evaluation :	A	Functional Evaluation :	A
<p>Remarks Defects not found</p>		<p>Remarks Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist</p>	

Inspector Notes
no warranty booklet/ no tools and jack/ with LTO plate and sparetire/