

General Information

Date & Time: 04, Feb, 2025 07:55

Make	Toyota	Model	Hiace
YOM	2023	Mileage	48,806
Registration No.	DBG9200	Chassis No.	JTFJT02P3P5033410
CC	3.0	Transmission	M/T
Fuel Type	Diesel	Type of Body	Van
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	110.2	107	125	99
2	Boot Lid	116.0	118	114	116
3	Roof	114.7	114	114	113/118
4	Left Front Fender	120.3	134	118	109
5	Left Front Door	108.0	105	108	111
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	105.4	111	109	96
9	Right Front Fender	109.6	101	111	117
10	Right Front Door	103.6	105	104	102
11	Center Panel Right	118.6	137	114	105
12	Right Rear Door	97.9	94	96	104
13	Right Back Panel	111.0	119	112	102

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Cut, Crack - Medium / Rear Seat - Grime - Large / Overall Interior - Smell - Yes	Remarks (R) Rear Fender, Molding - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Dent - Medium / (L) Rear Fender, Molding - Repair mark - Difference in Color / (L) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Repair mark - Difference in Color / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Roof - Dent - Small / (L) Front Wheel, Cover - Cap Missing - Yes / (L) Rear Wheel, Cover - Cap Missing - Yes / (R) Front Wheel, Cover - Cap Missing - Yes / (R) Rear Wheel, Cover - Cap Missing - Yes
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes

Inspector Notes

with warranty booklet/ with LTO plate/ no tools and jack/ with spare tire