

General Information

Date & Time: 23, Feb, 2026 14:46

Make	Suzuki	Model	Carry
YOM	2025	Odo Meter Reading	26,030
Registration No.	FAT5419	Chassis No.	MHYDC61TOTJ270960
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Van
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	98.9	106	92	99
2	Boot Lid	187.3	182	155	225
3	Roof				
4	Left Front Fender	105.0	103	109	103
5	Left Front Door	94.2	87	97	99
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	310.3	354	387	190
9	Right Front Fender	119.0	112	126	119
10	Right Front Door	100.1	97	101	103
11	Center Panel Right	101.6	100	104	101
12	Right Rear Door				
13	Right Back Panel	457.6	135	1,007	231

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Medium / Dashboard - Worn, Scratch, Cut, Crack - Small / (R) Front Seat - Grime - Small / (L) Front Trim - Grime - Small</p>	<p>Remarks (R) Front Door - Repair Traces - Yes / Front Panel - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (L) Rear Corner Panel - Repair Traces - Yes / (R) Rear Corner Panel - Repair Traces - Yes / Roof - Scratch - Medium / (R) Rear Door, Molding - Scratch - Small / (R) Side Gate - Rust, Corrosion - Small / Rear Gate - Scratch - Small / (L) Front Door, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Dent - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes</p>

Inspector Notes	
<p>With 2 Spare Key. With Spare Tire. No Warranty booklet. No seat cover. No jack and tools</p>	