

## General Information

Date & Time: 24, Feb, 2026 17:43

<b>Make</b>	Toyota	<b>Model</b>	Fortuner
<b>YOM</b>	2023	<b>Odo Meter Reading</b>	21,601
<b>Registration No.</b>	DBH2023	<b>Chassis No.</b>	MHFCB8GS5N0528528
<b>CC</b>	2.4	<b>Transmission</b>	A/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	SUV
<b>Colour</b>	Silver		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	128.3	119	137	129
2	Boot Lid	109.9	99	131	100
3	Roof	118.0	127	137	101/107
4	Left Front Fender	106.6	99	105	116
5	Left Front Door	115.6	120	113	114
6	Center Panel Left				
7	Left Rear Door	104.3	103	102	108
8	Left Back Panel	120.6	116	123	123
9	Right Front Fender	118.6	125	118	113
10	Right Front Door	121.6	121	121	123
11	Center Panel Right				
12	Right Rear Door	111.6	108	116	111
13	Right Back Panel	120.0	125	117	118

Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="color: red; font-weight: bold; font-size: 1.2em;">C</span>	<b>Exterior Evaluation :</b> <span style="color: red; font-weight: bold; font-size: 1.2em;">C</span>
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b>  (R) Front Trim - Grime - Small / (R) Front Floor Mat - Missing - Yes / Dashboard - Traces of Adhesive Tape - Yes / (R) Front Seat - Grime - Medium / (R) Rear Trim - Grime - Small / Ceiling - Grime - Small / (L) Rear Trim - Grime - Small / Rear Seat - Grime - Large / (L) Front Trim - Grime - Small / (L) Front Seat - Grime - Small / (L) Front Floor Mat - Missing - Yes / Sunvisor, Sunglass Holder - Grime - Minimal</p>	<p><b>Remarks</b>  (L) Front Fender, Molding - Scratch - Small / (L) Mirror - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Small / (R) Rear Door, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch &amp; Dent - Small / Front Bumper, Grille, Lamps - Scratch - Small</p>
<b>Frame Evaluation :</b> <span style="color: red; font-weight: bold; font-size: 1.2em;">A</span>	<b>Functional Evaluation :</b> <span style="color: red; font-weight: bold; font-size: 1.2em;">A</span>
<p><b>Remarks</b>  Defects not found</p>	<p><b>Remarks</b>  Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>Possible flooding. Gap at front bumper. Glove box issue. Unusual sound when opening upper glove box. Interior lights issue. Crack left taillight. Scratches at signal light, taillights and headlights. Without warranty booklet, jack and seat cover. With spare tire and tools. 1 key. No LTO plate. Temporary plate.</p>