

## General Information

Date & Time: 02, Mar, 2026 16:38

<b>Make</b>	Toyota	<b>Model</b>	Avanza
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	622
<b>Registration No.</b>	FAT1633	<b>Chassis No.</b>	MHFAA1BY8S0040327
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Wagon
<b>Colour</b>	Silver		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	102.2	104	99	104
2	Boot Lid	92.0	89	96	92
3	Roof	110.6	115	121	97/110
4	Left Front Fender	96.8	101	90	99
5	Left Front Door	114.3	100	121	122
6	Center Panel Left				
7	Left Rear Door	113.0	115	106	118
8	Left Back Panel	109.0	118	101	108
9	Right Front Fender	105.6	103	105	109
10	Right Front Door	111.3	118	113	103
11	Center Panel Right				
12	Right Rear Door	109.0	116	104	107
13	Right Back Panel	103.1	105	99	106

## Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">B</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<b>Remarks</b> (R) Front Trim - Cut, Crack - Medium / (L) Front Trim - Cut, Crack - Minimal / (L) Front Floor Mat - Grime - Large / Overall Interior - Smell - Yes	<b>Remarks</b> (R) Front Fender, Molding - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>
<b>Remarks</b> Defects not found	<b>Remarks</b> Spare Key - Issue - Unexist

<b>Inspector Notes</b>
With warranty booklet, with spare tire, with jack and tools, no LTO plate