

## General Information

Date & Time: 25, Feb, 2026 16:12

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	30,497
<b>Registration No.</b>	NKJ6320	<b>Chassis No.</b>	PA1B18F39R4266200
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Blue		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	104.3	100	107	106
2	Boot Lid	119.6	116	116	127
3	Roof	97.7	94	99	101/97
4	Left Front Fender	101.0	100	100	104
5	Left Front Door	108.3	107	106	112
6	Center Panel Left				
7	Left Rear Door	116.3	125	118	106
8	Left Back Panel	117.3	124	119	109
9	Right Front Fender	103.3	106	102	102
10	Right Front Door	106.0	109	106	103
11	Center Panel Right				
12	Right Rear Door	106.6	105	109	106
13	Right Back Panel	105.6	108	100	109

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b>	<b>B</b>	<b>Exterior Evaluation :</b>	<b>E</b>
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>		<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>	
<p><b>Remarks</b> Dashboard - Traces of Adhesive Tape - Yes / Ceiling - Grime - Minimal / (R) Front Seat - Grime - Minimal / (R) Front Trim - Grime - Minimal / Rear Seat - Grime - Small / (L) Front Seat - Worn - Yes</p>		<p><b>Remarks</b> (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch &amp; Dent - Large / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch &amp; Dent - Medium / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / Bonnet, Headlight - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Medium / Roof - Scratch - Medium</p>	
<b>Frame Evaluation :</b>	<b>A</b>	<b>Functional Evaluation :</b>	<b>B</b>
<p><b>Remarks</b> Defects not found</p>		<p><b>Remarks</b> Battery - Weak - Yes / Spare Key - Issue - Unexist</p>	

<b>Inspector Notes</b>
no warranty booklet and tools, with jack and tools and spare, with LTO plate, scratches on tail light, battery weak