

## General Information

Date & Time: 04, Mar, 2026 11:01

<b>Make</b>	Toyota	<b>Model</b>	Hilux Tamaraw
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	1,670
<b>Registration No.</b>	EAL3507	<b>Chassis No.</b>	PAHACACA4S6424308
<b>CC</b>	2.4	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	Dropside
<b>Colour</b>	White		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	106.0	111	104	103
2	Boot Lid	64.7	71	60	64
3	Roof	119.4	117	158	99/104
4	Left Front Fender	103.9	112	97	103
5	Left Front Door	99.2	97	101	100
6	Center Panel Left	95.6	103	100	84
7	Left Rear Door				
8	Left Back Panel	74.7	62	106	57
9	Right Front Fender	99.8	106	98	95
10	Right Front Door	97.8	94	100	100
11	Center Panel Right	103.6	111	103	97
12	Right Rear Door				
13	Right Back Panel	98.6	52	64	180

## Overall Evaluation :

**A**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="color: red; font-size: 24px; float: right;">A</span>	<b>Exterior Evaluation :</b> <span style="color: red; font-size: 24px; float: right;">C</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Roof - Repair Traces - Yes / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / (R) Center Panel - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch &amp; Dent - Medium / Rear Gate - Scratch - Minimal / Cargo Bed Floor - Scratch &amp; Dent - Small / (L) Side Gate - Scratch - Large / (L) Front Door, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Scratch - Minimal / Roof - Dent - Medium / (R) Side Gate - Scratch - Medium</p>
<b>Frame Evaluation :</b> <span style="color: red; font-size: 24px; float: right;">A</span>	<b>Functional Evaluation :</b> <span style="color: red; font-size: 24px; float: right;">A</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Reverse Camera - N/A - Yes</p>

<p><b>Inspector Notes</b></p>
<p>with warranty booklet, jack and tools, with spare tire and LTO PLATE, scratches on headlight</p>