

## General Information

Date & Time: 02, Mar, 2026 11:50

<b>Make</b>	Mitsubishi	<b>Model</b>	L300
<b>YOM</b>	2017	<b>Odo Meter Reading</b>	74,857
<b>Registration No.</b>	NAW1269	<b>Chassis No.</b>	PAEL35NYHGB003513
<b>CC</b>	2.5	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Diesel	<b>Type of Body</b>	FB Body
<b>Colour</b>	White		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	64.7	64	61	69
2	Boot Lid	111.3	107	119	108
3	Roof	56.6	59	56	59/53
4	Left Front Fender	90.3	87	70	114
5	Left Front Door	65.6	64	65	68
6	Center Panel Left	73.6	74	81	66
7	Left Rear Door				
8	Left Back Panel	99.4	89	72	137
9	Right Front Fender	81.0	98	74	71
10	Right Front Door	63.7	68	62	61
11	Center Panel Right	75.8	79	73	76
12	Right Rear Door				
13	Right Back Panel	84.0	71	75	106

## Overall Evaluation :

**D**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">C</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">E</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> Ceiling - Grime - Minimal / Sunvisor, Sunglass Holder - Grime - Medium / (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Carpet - Worn, Scratch, Cut, Crack - Large / (R) Front Trim - Loose, Deformed - Medium / (L) Front Trim - Loose, Deformed - Medium / Console, Switches, Vents - Loose, Deformed - Small</p>	<p><b>Remarks</b> (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch &amp; Dent - Large / (R) Step, In-panel, Side Spoiler - Scratch - Large / (R) Center Panel - Scratch - Minimal / (R) Side Gate - Scratch &amp; Dent - Medium / Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch &amp; Dent - Large / (L) Side Gate - Scratch &amp; Dent - Large / (L) Center Panel - Scratch &amp; Dent - Minimal / (L) Front Door, Molding - Scratch &amp; Dent - Medium / (L) Front Fender, Molding - Scratch &amp; Dent - Minimal / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Large / Front Panel - Scratch &amp; Dent - Minimal / Roof - Scratch &amp; Dent - Large</p>
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">B</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">D</span>
<p><b>Remarks</b> Front Floor and Side Member - Traces of Bending, or Marks of Panel Repair ? - Yes</p>	<p><b>Remarks</b> Panel, Meter - Issue - Yes / Air Conditioner - Function - Weak / Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>With Lto plate, with spare tire, 1key, no warranty booklet, no jack and tools, scratches on headlights, Crack taillight, battery weak, light switch issue</p>