

General Information

Date & Time: 27, Feb, 2026 18:56

Make	Toyota	Model	Wigo
YOM	2018	Odo Meter Reading	81,435
Registration No.	NCV6942	Chassis No.	NHKA4DF5FJJ03423
CC	1.0	Transmission	A/T
Fuel Type	Gas	Type of Body	Hatchback
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	86.1	79	104	75
2	Boot Lid	91.0	88	97	88
3	Roof	69.0	60	75	71/71
4	Left Front Fender	141.6	181	141	103
5	Left Front Door	82.8	76	87	85
6	Center Panel Left				
7	Left Rear Door	83.7	86	86	80
8	Left Back Panel	73.3	80	69	70
9	Right Front Fender	84.5	86	85	82
10	Right Front Door	82.3	81	88	78
11	Center Panel Right				
12	Right Rear Door	252.0	201	391	164
13	Right Back Panel	227.6	162	234	287

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	B	Exterior Evaluation :	C
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Small / Dashboard - Worn, Scratch, Cut, Crack - Minimal / Console, Switches, Vents - Worn, Scratch, Cut, Crack - Small / Ceiling - Cut, Crack - Minimal / Trunk Room - Worn, Scratch, Cut, Crack - Medium</p>		<p>Remarks (L) Front Fender - Repair Traces - Yes / (R) Rear Fender - Repair Traces - Yes / (R) Rear Door - Repair Traces - Yes / (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Modified - Small / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Repair mark - Yes / (R) Rear Door, Molding - Scratch & Dent - Minimal / (R) Rear Fender, Molding - Repair mark - Yes / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch & Dent - Minimal / (L) Rear Door, Molding - Scratch & Dent - Minimal / (L) Front Door, Molding - Scratch & Dent - Minimal / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Repair mark - Yes / (L) Front Fender, Molding - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Repair mark - Difference in Color / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Modified - Small / Roof - Crack, Gap - Small</p>	
Frame Evaluation :	A	Functional Evaluation :	A
<p>Remarks Defects not found</p>		<p>Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>	

Inspector Notes
With Lto plate, with jack, 1key, no warranty booklet, no spare tire and tools, scratches on headlights and taillights,