

## General Information

Date & Time: 27, Feb, 2026 18:55

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2021	<b>Odo Meter Reading</b>	40,609
<b>Registration No.</b>	DAV7954	<b>Chassis No.</b>	PA1B1837M4152317
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Silver		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	180.3	179	186	176
2	Boot Lid	190.3	186	176	209
3	Roof	109.2	116	111	105/105
4	Left Front Fender	112.3	109	109	119
5	Left Front Door	124.6	123	126	125
6	Center Panel Left				
7	Left Rear Door	162.0	175	166	145
8	Left Back Panel	137.3	141	132	139
9	Right Front Fender	150.6	150	147	155
10	Right Front Door	116.3	114	114	121
11	Center Panel Right				
12	Right Rear Door	122.6	122	123	123
13	Right Back Panel	127.6	124	124	135

## Overall Evaluation :

**C**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="color: red; font-weight: bold;">C</span>	<b>Exterior Evaluation :</b> <span style="color: red; font-weight: bold;">C</span>
 <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	 <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<p><b>Remarks</b> Ceiling - Grime - Minimal / (R) Front Trim - Grime - Minimal / (L) Front Seat - Grime - Minimal / Trunk Room - Loose, Deformed - Large</p>	<p><b>Remarks</b> Bonnet - Repair Traces - Yes / Trunk Hood, Rear Gate - Repair Traces - Yes / (R) Front Fender, Molding - Repair mark - Yes / (R) Front Fender, Molding - Scratch &amp; Dent - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch &amp; Dent - Minimal / Trunk Hood, Rear Gate - Scratch &amp; Dent - Minimal / (L) Rear Fender, Molding - Scratch &amp; Dent - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch &amp; Dent - Small / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Medium / Front Bumper, Grille, Lamps - Repair mark - Yes / Bonnet, Headlight - Scratch - Minimal / Roof - Scratch &amp; Dent - Minimal</p>
<b>Frame Evaluation :</b> <span style="color: red; font-weight: bold;">C</span>	<b>Functional Evaluation :</b> <span style="color: red; font-weight: bold;">B</span>
<p><b>Remarks</b> Front Cross Member Support - Traces of Bending, or Marks of Panel Repair ? - Yes / Right Front Inside Panel (Front Side) - Traces of Bending, or Marks of Panel Repair ? - Yes</p>	<p><b>Remarks</b> Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>With Lto plate, with jack, 1key, no warranty booklet, no spare tire and tools, cover under hood missing, trunk cover missing, bumper logo and hook cover missing</p>