

General Information

Date & Time: 02, Mar, 2026 16:35

Make	Suzuki	Model	S-Presso
YOM	2025	Odo Meter Reading	7,445
Registration No.	FAT5272	Chassis No.	MA3FL61SXSA532077
CC	1.0	Transmission	A/T
Fuel Type	Gas	Type of Body	Hatchback
Colour	White		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	163.3	137	175	178
2	Boot Lid	101.6	105	100	100
3	Roof	137.5	148	140	138/124
4	Left Front Fender	205.0	193	194	228
5	Left Front Door	127.3	153	120	109
6	Center Panel Left				
7	Left Rear Door	104.0	103	98	111
8	Left Back Panel	115.6	110	123	114
9	Right Front Fender	107.3	108	110	104
10	Right Front Door	104.8	98	104	113
11	Center Panel Right				
12	Right Rear Door	98.6	101	93	102
13	Right Back Panel	113.0	104	114	121

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	A	Exterior Evaluation :	C
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks (R) Front Seat - Grime - Small / (R) Front Trim - Grime - Small / Rear Seat - Grime - Small</p>		<p>Remarks (L) Front Fender - Repair Traces - Yes / Trunk Hood, Rear Gate - Dent - Large / (R) Front Door, Molding - Scratch - Medium / (R) Front Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small</p>	
Frame Evaluation :	A	Functional Evaluation :	A
<p>Remarks Defects not found</p>		<p>Remarks Defects not found</p>	

Inspector Notes
NO LTO PLATE. With Spare Tire, with 1 spare key. with seat cover.no warranty booklet