


General Information

Date & Time: 16, Mar, 2026 13:51

Make	Mitsubishi	Model	Mirage
YOM	2025	Odo Meter Reading	11,783
Registration No.	NHT1155	Chassis No.	PAEA13RXSRA000303
CC	1.2	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	130.0	135	131	124
2	Boot Lid	103.8	99	116	97
3	Roof	110.5	112	112	106/112
4	Left Front Fender	117.0	118	123	110
5	Left Front Door	104.6	102	107	105
6	Center Panel Left				
7	Left Rear Door	105.3	106	103	107
8	Left Back Panel	110.6	100	121	111
9	Right Front Fender	110.0	118	108	104
10	Right Front Door	112.6	113	112	113
11	Center Panel Right				
12	Right Rear Door	109.6	111	105	113
13	Right Back Panel	115.3	104	114	128

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	C	Exterior Evaluation :	D
The diagram shows the interior of a vehicle from above. Numbered areas include: 1 (front floor mats), 2 (rear seat area), 3 (center console), 4 (driver's side door panel), 5 (passenger's side door panel), 6 (rear passenger area), 7 (rear bench seat), 8 (rear floor mat), 9 (driver's seat), and 10 (passenger's seat). Lettered codes are placed near specific components: 'X' at the top of the front seats, 'Y' on the rear bench seat, and 'Z' on the center console.		The diagram shows the exterior of a vehicle from three perspectives: front, side, and rear. Numbered areas include: 1 (front bumper), 2 (front grille), 3 (front headlight), 4 (front fender), 5 (front door), 6 (rear door), 7 (rear fender), 8 (rear bumper), 9 (rear tailgate), 10 (left wheel arch), 11 (right wheel arch), 12 (left mirror), 13 (hood), 14 (roof), 15 (trunk), 16 (left door handle), 17 (right door handle), 18 (left door hinge), 19 (right door hinge), 20 (left door latch), 21 (right door latch), 22 (left door trim), 23 (right door trim), 24 (left door weatherstripping), 25 (right door weatherstripping).	
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain		A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap	
Remarks (R) Front Floor Mat - Missing - Yes / (L) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / (R) Front Seat - Grime - Medium / Rear Seat - Grime - Minimal / Display, Audio System - Partially Missing - Yes		Remarks Bonnet, Headlight - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Front Door, Molding - Scratch - Large / (R) Front Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (L) Rear Fender, Molding - Dent - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small	
Frame Evaluation :	A	Functional Evaluation :	B
Remarks Defects not found		Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist	

Inspector Notes

no warranty booklet/ incomplete tools/ with jack and spare tire/ with LTO plate/