

General Information

Date & Time: 04, May, 2026 16:16

Make	Suzuki	Model	XL7
YOM	2025	Odo Meter Reading	27,153
Registration No.	GBJ6600	Chassis No.	MHYNC32S7TJ100023
CC	1.5	Transmission	A/T
Fuel Type	Gas	Type of Body	Wagon
Colour	Gray		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	87.2	103	69	90
2	Boot Lid	88.8	86	86	95
3	Roof	79.7	72	76	86/85
4	Left Front Fender	81.6	78	79	88
5	Left Front Door	89.6	92	80	96
6	Center Panel Left				
7	Left Rear Door	90.4	96	85	90
8	Left Back Panel	84.5	86	86	82
9	Right Front Fender	82.3	87	80	81
10	Right Front Door	93.5	93	91	97
11	Center Panel Right				
12	Right Rear Door	95.7	93	89	105
13	Right Back Panel	88.0	89	83	92

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Small / (R) Front Trim - Grime - Small / (R) Front Seat - Grime - Small / Ceiling - Grime - Small / (L) Rear Trim - Grime - Small	Remarks (L) Front Door, Molding - Scratch & Dent - Large / (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch - Small / (R) Front Door, Molding - Dent - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes

visible hairline scratches on left rear door. With Spare tire. With Spare key. No warranty booklet. No Seat cover.