

General Information

Date & Time: 09, May, 2026 18:45

Make	Ford	Model	Everest
YOM	2018	Odo Meter Reading	75,038
Registration No.	NBE8743	Chassis No.	MNCAXXMAWAJS21920
CC	2.2	Transmission	A/T
Fuel Type	Diesel	Type of Body	SUV
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	110.0	110	113	107
2	Boot Lid	110.6	107	113	112
3	Roof	126.0	121	121	123/139
4	Left Front Fender	116.6	118	122	110
5	Left Front Door	112.0	122	103	111
6	Center Panel Left				
7	Left Rear Door	133.6	141	135	125
8	Left Back Panel	123.6	124	126	121
9	Right Front Fender	137.3	119	152	141
10	Right Front Door	112.6	114	106	118
11	Center Panel Right				
12	Right Rear Door	113.3	113	105	122
13	Right Back Panel	120.0	124	115	121

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	B	Exterior Evaluation :	D
The diagram shows the interior of a vehicle from a top-down perspective. Evaluation points are marked as follows: D3 at the front dashboard area, A3 on the driver's seat, D2 on both side door panels, 2 on the rear headrest area, 4 on the rear seat headrests, 5 on the rear seat cushion, 3 on the center console, 7 on the front passenger seat, and 8 on the front floor area.	a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	The diagram shows the exterior of a vehicle from a top-down perspective. Evaluation points are marked as follows: AU3 on the front hood, A2 on the front fenders, B3 on the front doors, 9 on the front door handle area, 15 on the rear trunk lid, and 3 on the rear door handle area.	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Trim - Worked - Small / (R) Front Trim - Worked - Small / Sunvisor, Sunglass Holder - Loose, Deformed - Medium / (L) Front Seat - Cut, Crack - Medium		Remarks (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / (R) Step, In-panel, Side Spoiler - Modified - Medium / (L) Front Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch & Dent - Medium / (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Modified - Medium / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / Bonnet, Headlight - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small	
Frame Evaluation :	A	Functional Evaluation :	B
Remarks Defects not found		Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Spare Key - Issue - Unexist	

Inspector Notes

With LTO plate, no warranty booklet, incomplete tools, with jack, with spare tire, no spare key, with hairline scratches, no reverse camera, loose handle (driver side), not functioning parklight (front right).