

General Information

Date & Time: 21, Feb, 2025 14:40

Make	Suzuki	Model	Carry
YOM	2023	Mileage	15,137
Registration No.	NHE7290	Chassis No.	MHYDC61TXPJ213154
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Van
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	495.3	197	206	1,083
2	Boot Lid	151.0	181	128	144
3	Roof	106.3	115	109	92/109
4	Left Front Fender	342.6	260	221	547
5	Left Front Door	111.6	117	114	104
6	Center Panel Left	102.4	102	106	99
7	Left Rear Door				
8	Left Back Panel	165.0	198	120	177
9	Right Front Fender	147.6	133	153	157
10	Right Front Door	108.3	111	112	102
11	Center Panel Right	110.3	120	104	107
12	Right Rear Door				
13	Right Back Panel	180.3	161	134	246

Overall Evaluation :

C

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Overall Interior - Smell - Yes / (R) Rear Trim - Worked - Large / (L) Rear Trim - Worked - Large	Remarks (R) Front Door - Repair Traces - Yes / Front Panel - Repair Traces - Yes / (L) Front Door - Repair Traces - Yes / (L) Rear Corner Panel - Repair Traces - Yes / (R) Rear Corner Panel - Repair Traces - Yes / Roof - Repair Traces - Yes / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Wheel, Cover - Scratch, Corrosion - Bent / (L) Side Gate - Scratch & Dent - Large / (L) Front Door, Molding - Scratch - Medium / Front Panel - Dent - Small / Front Bumper, Grille, Lamps - Scratch - Large / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Medium / (R) Side Gate - Scratch - Large / Roof - Dent - Large
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes

Inspector Notes

without LTO plate / with spare tire/ no warranty booklet/ No jack and tools