

General Information

Date & Time: 19, May, 2026 17:01

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	16,740
Registration No.	GBK9852	Chassis No.	PA1B18F35S4292279
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blackish Red Mica		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	119.6	113	119	127
2	Boot Lid	115.0	112	104	129
3	Roof	108.6	109	101	99/125
4	Left Front Fender	109.3	107	112	109
5	Left Front Door	124.0	115	121	136
6	Center Panel Left				
7	Left Rear Door	107.0	105	107	109
8	Left Back Panel	126.0	130	131	117
9	Right Front Fender	100.0	99	100	101
10	Right Front Door	108.0	106	103	115
11	Center Panel Right				
12	Right Rear Door	104.3	101	104	108
13	Right Back Panel	112.3	110	111	116

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	D
The diagram shows the interior of a vehicle from a top-down perspective. The front seats are labeled with Y2 and Y3. The rear seat is labeled with Y2. The center console is labeled with D3. The floor mats are labeled with 8.	The diagram shows the exterior of a vehicle from a top-down perspective. The front end is labeled with AU4 and A4. The side mirrors are labeled with A4. The rear door is labeled with A2. The rear bumper is labeled with AU3. The trunk area is labeled with 13.
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks	Remarks
Overall Interior - Animal Hair - Yes / (R) Front Trim - Grime - Small / (R) Front Floor Mat - Grime - Small / (L) Front Floor Mat - Grime - Medium / (R) Front Seat - Grime - Small / Rear Seat - Grime - Medium / (R) Rear Trim - Grime - Small / (L) Rear Trim - Grime - Small / (L) Front Trim - Grime - Small / (L) Front Seat - Grime - Medium / Mat Other - Grime - Small / Ceiling - Grime - Small / Glove Box - Loose, Deformed - Medium	(L) Front Fender, Molding - Scratch & Dent - Large / (L) Front Door, Molding - Scratch & Dent - Large / (L) Mirror - Scratch - Small / (L) Rear Door, Molding - Scratch & Dent - Large / (L) Rear Fender, Molding - Scratch & Dent - Large / Trunk Hood, Rear Gate - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Large / (R) Front Door, Molding - Scratch - Large / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Large / (R) Mirror - Scratch - Small / (R) Front Fender, Molding - Scratch - Large / Front Bumper, Grille, Lamps - Scratch & Dent - Large / Bonnet, Headlight - Scratch - Large / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Medium
Frame Evaluation :	B
Remarks	Remarks
Front Cross Member Support - Traces of Bending, or Marks of Panel Repair ? - Yes	Defects not found

Inspector Notes

Possible flooded. Damage front bumper to rear fender. Left front door issue. Left side mirror loosen. Gap at right rear bumper. Crack at right taillight. Visible hairline scratches. With Warranty booklet, seatcover, tools, jack, spare tire, LTO plate and 2 keys.