


General Information

Date & Time: 23, May, 2026 15:45

Make	Suzuki	Model	Carry
YOM	2022	Odo Meter Reading	35,291
Registration No.	NHB5004	Chassis No.	MHYDC61T0PJ210750
CC	1.5	Transmission	M/T
Fuel Type	Gas	Type of Body	Wagon
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	115.0	114	106	125
2	Boot Lid	142.3	135	140	152
3	Roof	153.6	98	121	94/301
4	Left Front Fender	138.6	139	150	127
5	Left Front Door	117.6	113	120	120
6	Center Panel Left	126.3	124	120	135
7	Left Rear Door				
8	Left Back Panel	145.0	130	152	153
9	Right Front Fender	160.3	136	144	201
10	Right Front Door	111.3	108	113	113
11	Center Panel Right	109.6	117	106	106
12	Right Rear Door				
13	Right Back Panel	145.3	160	168	108

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Seat - Grime - Small / (R) Front Seat - Grime - Small / Rear Seat - Grime - Small / (L) Front Trim - Grime - Small / (R) Front Trim - Grime - Small / (L) Front Floor Mat - Crinkle - Small / (R) Front Floor Mat - Grime - Small	Remarks Front Panel - Replaced - Yes / Roof - Repair Traces - Yes / (R) Side Gate - Scratch & Dent - Small / (R) Front Door, Molding - Scratch & Dent - Small / (R) Center Panel - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Small / Front Panel - Scratch - Small / (L) Front Fender, Molding - Scratch & Dent - Minimal / (R) Front Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch & Dent - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Center Panel - Scratch - Minimal / Overall Exterior - Faded(Color, Gloss) - Yes / Roof - Dent - Medium / (L) Side Gate - Rust, Corrosion - Medium / Rear Gate - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / Cargo Bed Floor - Scratch & Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

with LTO plate, with spare tire, with warranty and manual booklet, no jack and tools, no spare key scratches on exterior, scratches on taillight and headlight.