

General Information

Date & Time: 19, Feb, 2025 17:32

Make	Suzuki	Model	Dzire
YOM	2022	Mileage	26,456
Registration No.	NFL3264	Chassis No.	MBHZF63S6NG163475
CC	1.2	Transmission	A/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	100.3	100	100	101
2	Boot Lid	85.1	93	83	80
3	Roof	110.1	100	96	115/130
4	Left Front Fender	104.3	106	107	100
5	Left Front Door	101.6	103	102	100
6	Center Panel Left				
7	Left Rear Door	95.0	99	95	92
8	Left Back Panel	99.3	100	102	96
9	Right Front Fender	99.7	101	100	98
10	Right Front Door	96.5	95	98	97
11	Center Panel Right				
12	Right Rear Door	90.2	86	90	95
13	Right Back Panel	99.1	98	99	101

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : C
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Dashboard - Traces of Adhesive Tape - Yes / (R) Front Seat - Grime - Medium / Mat Other - Grime - Small / Rear Seat - Grime - Small / Ceiling - Grime - Minimal / Console, Switchs, Vents - Traces of Adhesive Tape - Yes	Remarks (L) Front Fender, Molding - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Front Fender, Molding - Dent - Small / (R) Rear Door, Molding - Scratch - Large / (R) Rear Fender, Molding - Scratch & Dent - Small / (L) Rear Door, Molding - Scratch - Small / Trunk Hood, Rear Gate - Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

with warranty booklet, spare tire, jack but incomplete tools. with LTO plate